



County of El Paso Purchasing Department
800 E. Overland Room 300
El Paso, Texas 79901
(915) 546-2048 / Fax: (915) 546-8180

ADDENDUM 1

To: All Interested Proposers

From: Linda Gonzalez, Inventory Bid Technician

Date: January 06, 2008

Subject: RFP # 08-176, (RFP) Inspect and Repair the Exhaust Duct from the Boiler Room -12th Floor at the Detention Facility

The Purchasing Department received questions relating to the above referenced proposal; the response to the following question:

1. I need the dimensions for the following:
 - 5 each, Boiler Exhaust Flues
 - 1 each, Bakery Rotary Oven Flue
 - 1 each, Bakery Hood Exhaust
 - 1 each, Kitchen Hood Exhaust
 - 1 each, Kitchen Steam Kettle Hood Exhaust

The dimensions are as follows:

- 3 each Bryan Boilers, 15 ¼"
- 2 each Cleaver Brooks Heating boilers, 15 ¾"
- Kitchen Hood system, 28" x 48"
- Kitchen steam kettle, 15" x 20"
- Bakery rotary oven hood, 10 "
- Bakery hood system, 12" x 24"

RFP# 08-176, (RFP) Inspect and Repair the Exhaust Duct from the Boiler Room - 12th Floor at the Detention Facility

2. The above description states inspect and repair. The Scope of work (page 5) states inspection only. Please confirm that this proposal is for inspection only with recommendation for repair.

Please Note: the following is the correct statement for this RFP #08-176

(RFP) Inspect and submit an estimate for the repair of the Exhaust Ducts between the Basement Boiler Room and the 12th Floor at the Detention Facility